

CONDITION REPORT : ROUGHTERRAINE CRANE

Model. Serial No : KR35H-V2-2410153 Mfg Year : 2004yr March Serial number plate : ()
 Chassis No : KR353-0153 Engrave No. () Travelling Distance : 46,226km
 Engine No : 6D24-341922 Engrave No. () Hour Meter : 18,471hr
 Specification : Outrigger (H) Jib; 2 section (PJ) A/C () No) Belt makes sound during operation

Hook : 3 pcs - 35t, 22.5t, Ball (socket-not original) see photo no. 604-605
 Camera monitor: () Yes No () Side () Rear () Winch Condition : OK (not original)
 Engine : Starting : () Normal Oil : () Normal Short/ Dirty
 Battery : Normal/ Need to charge Coolant : () Normal Short/ Dirty
 Oil leakage : () No

(Inspection point)

Computer: Normal/Display not good/ Display panel broken / Emergency stop (Relief key missing) / () Overwinding Error sign does not stop !

Main Pump: () Normal Abnormal/ Power weak / Oil leaking

Boom: Normal / Vibration on expansion and contraction shortage of grease / Inclination at full expansion / Dent / crack
 *Repair trace on Top boom

Derick cylinder: () Normal Abnormal/ Rod scratch, dent/ Natural drop/Oil leakage

Telecylinder: () Normal Abnormal/ Natural drop/ Oil leakage

Winch/ Motor: () Normal Abnormal/ Freefall -not good (Main Sub)/ Oil leakage

Wire rope: Main : () Normal Kink/ Rough/ Rusty/ Short Sub: () Normal Kink/ Rough/ Rusty/ Short

Swing/ Rotary: Normal/ Abnormal/ Oil leakage Bearing loose: Horizontal loose: (Big, () Middle, Small)

Vertical loose : (Big, Middle, () Small)

Outrigger: () Vertical / Horizontal) : Normal / Scratch on rod/ Deform/ () Oil leakage -3pcs- see photo no.569

Valve / Hose ; Normal/ Oil leakage/ Hose Degraded(() Yes) No)

Travelling / Brake : Normal / Exhaust gas brake () / Special travelling () / Suspension ()

Torque converter / transmission : Normal/ Abnormal sound(yes () No) / () 4WD Oil volume: () Normal/ Need to fulfill

Oil leakage: (Yes () No)

Tire Size/ Condition: 445/95/R25	3	3
	3	4

Remark : Some places of crane cover are damaged.
 Boom expansion wire- some kink (see photo no 650)
 Top boom- repaired, a bit twisted (see photo no.580-641)
 Electric-retractable mirror -left and right- not working

(日新L-8)

油圧クレーン査定表

23年4月13日

型式 号機	KR35H-V2-2710153	2004年 3月製	銘板 (○)
シャーシ番号	KR353-0153	刻印(○)	走行距離 46,226 Km
エンジン番号	6C24-341922	刻印(○)	稼働時間 18,471 Hr
仕様	アウトリガ (H (X))	ジブ2段 (PJ (STD))	A/C (有) 無し
フック 3個	35t, 22.5t, ホール(リフト-5t ^{1/2})		敷板 (P~604~605) X 枚
カメラ モニター	(有) 無し	ウインチ	敷鉄板 X 枚
エンジン	状態: OK (5t ^{1/2})		
始動状態	(正常)	オイル	(正常) / 不足 / 白濁
バッテリー	(正常) / 不良	冷却水	(正常) / 不足 / 汚れ
油漏れ	(無し)		

査定項目	摘要	写真 (P~)
コンピュータ	正常 / 画面不良 / パネル割れ / 非常停止 (解除キー欠品) / (過巻き) / エラー表示	停止 (2枚)
メインポンプ	(正常) 異音 / パワー不足 / 油漏れ	
ブーム	正常 / 伸縮時振動 / クリス切れ / 全長時傾き / 凹み / 割れ	TOPブーム修正跡 (P~637~643)
デリックシリンダー	(正常) 異音 / ロッド傷 / 凹み / 自然降下 / 油漏れ	
テレスリンダー	(正常) 異音 / 自然降下 / 油漏れ	
ウインチ / モーター	(正常) 異音 / フリーホール不良 (主補) / 油漏れ	
ワイヤーロープ	主巻: (正常) / キンク 粗線 錆 長さ不足 補巻: (正常) / キンク 粗線 錆 長さ不足	
旋回 / ロータリー	正常 / 異音 / 油漏れ	ベアリングのガタ: 横ガタ (大 (中) 小) : 縦ガタ (大 中 (小))
アウトリガ (縦 / 横)	正常 / ロッド傷 変形 / 油漏れ	2本 (P~569)
バルブ / ホース類	正常 / 油漏れ / ホース老化 (有) 無し	
走行 / ブレーキ	正常 / 排気ブレーキ (○) / リターダブレーキ () / 特殊走行 (○) / サスペンション (○)	実走できず
トルコン / ミッション	正常 / 異音 (有 (無)) / 2-4WD切替 () / スリップテスト (←) / OIL量 (正常) 要補充 / 油漏れ (有 (無))	
他の油漏れカ所	サスペンションC/L / ステアリングC/L /	

タイヤ状態 サイズ
445/95R25

特記
 グレックカバー-割れ有り
 ブーム伸縮ワイヤー-2本有り (P~650)
 TOPブーム修正跡、少し曲がってる (P~580~641)
 規格ミシ- 左右不良

取説 (クレーン エンジン) パーツブック (クレーン エンジン)