

BULLDOZER

MAKER	KOMATSU	HOUR	4698	H
MODEL	D31P-18	YEAR	1989	
SERIAL	42542			

SPECIFICATION

BLADE	STATE				TYPE				
	<input type="checkbox"/> A	<input type="checkbox"/> B	<input checked="" type="checkbox"/> C	<input type="checkbox"/> D	<input type="checkbox"/> STRAIGHT	<input type="checkbox"/> ANGLE	<input checked="" type="checkbox"/> 6-WAY	<input type="checkbox"/> NONE	
OPERATOR'S PLACE		<input type="checkbox"/> CABIN	<input checked="" type="checkbox"/> CANOPY	<input type="checkbox"/> W/O CANOPY					
RIPPER	<input type="checkbox"/> M/S	<input type="checkbox"/> S/S	()	<input type="checkbox"/> NONESHANK	<input type="checkbox"/> YES () PCS				
PUSH-ARM	<input type="checkbox"/> A	<input type="checkbox"/> B	<input checked="" type="checkbox"/> C	<input type="checkbox"/> D	()				
PIN-BOSS	<input type="checkbox"/> A	<input type="checkbox"/> B	<input checked="" type="checkbox"/> C	<input type="checkbox"/> D	()				
COMMENT									

ENGINE

MAKER & MODEL	KOMATSU 6D95L				
ENGINE OIL	<input checked="" type="checkbox"/> OK	<input type="checkbox"/> NG ()	EXHAUST COLOR	<input checked="" type="checkbox"/> OK	<input type="checkbox"/> NG ()
RADIATOR	<input checked="" type="checkbox"/> OK	<input type="checkbox"/> NG ()	ENGINE SOUND	<input checked="" type="checkbox"/> OK	<input type="checkbox"/> NG ()
BATTERY	<input type="checkbox"/> OK	<input checked="" type="checkbox"/> NG (Battery - Flat (バッテリー-上がり))			
OIL LEAKAGE	<input checked="" type="checkbox"/> NONE ()	BLOW-BY		<input type="checkbox"/> OK	<input type="checkbox"/> NG (C)
COMMENT					

HYDRAULIC PART

LIFT CYLINDER	<input type="checkbox"/> OK	<input checked="" type="checkbox"/> OIL LEAKAGE	<input type="checkbox"/> OTHER (SMUDGE)	HOSE - oil leak (ホース-オイル漏)	
ANGLE CYLINDER	<input type="checkbox"/> OK	<input checked="" type="checkbox"/> OIL LEAKAGE	<input type="checkbox"/> OTHER ()	Left & Right (左右) (7/10)	
RIPPER CYLINDER	<input type="checkbox"/> OK	<input type="checkbox"/> OIL LEAKAGE	<input type="checkbox"/> OTHER ()		
TILT CYLINDER	<input checked="" type="checkbox"/> OK	<input type="checkbox"/> OIL LEAKAGE	<input type="checkbox"/> OTHER ()		
MAIN PUMP	<input checked="" type="checkbox"/> OK	<input type="checkbox"/> NG ()			
DAMAGE OF HYDRAULIC HOSE	<input type="checkbox"/> NONE	<input type="checkbox"/> OTHER (C)			
DEFORM OF HYDRAULIC PIPE	<input type="checkbox"/> NONE	<input type="checkbox"/> OTHER (C)			

TRAVELLING PART


	LEFT	RIGHT
TRAVELLING MOTOR & GEAR	<input checked="" type="checkbox"/> OK	<input checked="" type="checkbox"/> OK
PIN BUSH	<input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	<input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D
TRUCK LINK	<input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	<input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D
ADJUSTMENT	<input type="checkbox"/> OK <input type="checkbox"/> NG ()	
SHOE	WIDTH (600)mm L&R	
CARRIER ROLLER	<input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
TRACK ROLLER	○ ○ ○ ○ ○ ○ ○	○ ○ ○ ○ ○ ○ ○
COMMENT		

BODY


PAINT	<input type="checkbox"/> GENUINE	<input type="checkbox"/> REPAINT	<input type="checkbox"/> OTHER ()						
RUST ON BODY	<input type="checkbox"/> A	<input type="checkbox"/> B	<input checked="" type="checkbox"/> C	<input type="checkbox"/> D	CAB / CANOPY	<input type="checkbox"/> A	<input type="checkbox"/> B	<input checked="" type="checkbox"/> C	<input type="checkbox"/> D
CRACK, DEFORMATION OF FRAME	<input type="checkbox"/> A	<input type="checkbox"/> B	<input checked="" type="checkbox"/> C	<input type="checkbox"/> D	OPERATOR'S SEAT	<input type="checkbox"/> A	<input type="checkbox"/> B	<input checked="" type="checkbox"/> C	<input type="checkbox"/> D

OPERATION COMPONENT

THROTTLE	<input checked="" type="checkbox"/> OK	<input type="checkbox"/> NG ()			
STEERING	<input checked="" type="checkbox"/> OK	<input type="checkbox"/> NG ()			
FOOT BRAKE	<input checked="" type="checkbox"/> OK	<input type="checkbox"/> NG ()			
PARKING BRAKE	<input type="checkbox"/> OK	<input type="checkbox"/> NG ()			
LCD MONITOR	<input type="checkbox"/> OK	<input type="checkbox"/> NG ()	<input type="checkbox"/> NONE		
CONTROL LEVER	<input checked="" type="checkbox"/> OK	<input type="checkbox"/> NG ()			
TRANSMISSION	<input type="checkbox"/> DD	<input checked="" type="checkbox"/> PS	<input type="checkbox"/> DPS	<input type="checkbox"/> HST	<input type="checkbox"/> DFS
	FRONT	(3) SPEED	BACK	(3) SPEED	



DAMAGE (損傷)



左右 机油漏出 (OIL LEAK) Left & Right