

BULLDOZER

MAKER	KOMATSU	HOUR	1363	H
MODEL	D31A-20	YEAR	1995	
SERIAL	42380			

SPECIFICATION

BLADE	STATE		TYPE	
	☐ A ☐ B ☒ C ☐ D	☐ STRAIGHT ☐ STRAIGHT	☐ ANGLE ☐ OTHER ()	☒ 6-WAY ☐ NONE
OPERATOR'S PLACE		☐ CABIN ☒ CANOPY	☐ W/O CANOPY	
RIPPER	☐ M/S ☐ S/S ()	☐ NONESHANK	☐ YES () PCS	
PUSH-ARM	☐ A ☐ B ☒ C ☐ D ()			
PIN-BOSS	☐ A ☐ B ☒ C ☐ D ()			
COMMENT				

ENGINE

MAKER & MODEL		KOMATSU / 6D95L	
ENGINE OIL	☒ OK ☐ NG ()	EXHAUST COLOR	☒ OK ☐ NG ()
RADIATOR	☒ OK ☐ NG ()	ENGINE SOUND	☒ OK ☐ NG ()
BATTERY	☒ OK ☐ NG ()		
OIL LEAKAGE	☒ NONE ()	BLOW-BY	☒ OK ☐ NG ()
COMMENT			

HYDRAULIC PART

LIFT CYLINDER	☒ OK ☐ OIL LEAKAGE ☐ OTHER ()
ANGLE CYLINDER	☐ OK ☐ OIL LEAKAGE ☐ OTHER () LEFT-oil smudge
RIPPER CYLINDER	☐ OK ☐ OIL LEAKAGE ☐ OTHER ()
TILT CYLINDER	☒ OK ☐ OIL LEAKAGE ☐ OTHER ()
MAIN PUMP	☒ OK ☐ NG ()
DAMAGE OF HYDRAULIC HOSE	☒ NONE ☐ OTHER ()
DEFORM OF HYDRAULIC PIPE	☒ NONE ☐ OTHER ()

TRAVELLING PART

	LEFT	RIGHT
TRAVELLING MOTOR & GEAR	☒ OK ☐ NG ()	☒ OK ☐ NG ()
PIN BUSH	☐ A ☐ B ☒ C ☐ D	☐ A ☐ B ☒ C ☐ D
TRUCK LINK	☐ A ☐ B ☒ C ☐ D	☐ A ☐ B ☒ C ☐ D
ADJUSTMENT	☒ OK ☐ NG ()	
SHOE	WIDTH (330)mm	
CARRIER ROLLER	☐ A ☐ B ☒ C ☐ D	
TRACK ROLLER	○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○	
COMMENT		

BODY

PAINT	☐ GENUINE ☐ REPAINT ☐ OTHER ()
RUST ON BODY	☐ A ☐ B ☐ C ☐ D CAB / CANOPY ☐ A ☐ B ☐ C ☐ D
CRACK, DEFORMATION OF FRAME	☐ A ☐ B ☐ C ☐ D OPERATOR'S SEAT ☐ A ☐ B ☐ C ☐ D

OPERATION COMPONENT

THROTTLE	☐ OK ☐ NG ()
STEERING	☐ OK ☐ NG ()
FOOT BRAKE	☐ OK ☐ NG ()
PARKING BRAKE	☐ OK ☐ NG ()
LCD MONITOR	☐ OK ☐ NG () ☐ NONE
CONTROL LEVER	☐ OK ☐ NG ()
TRANSMISSION	☐ DD ☐ PS ☐ DPS ☐ HST ☐ DFS FRONT (3) SPEED BACK (3) SPEED

